



January 31 , 2025

Audience: CLEC,ISP,IXC,Resellers,Wireless,ILEC

Subject : Verizon Partner Solutions Industry Letter: West 36th 2 St. NY 5E Switch Retirement

PLEASE NOTE:

- All references to the West 36th St. 2 NY 5E switch are associated with CLLI code NYCMNY36DS1 and will not be repeated throughout this letter.
- All references to the Pearl St. NY C20 switch are associated with CLLI code NYCMNYPSPS1 and will not be repeated throughout this letter.

As set out in the Verizon New York Inc. Short Term Public Notice Under Rule 51.333(a), dated January 31, 2025, on or after June 1, 2025, the West 36th St. 2 NY 5E switch will be retired and removed from the Verizon network as part of ongoing efforts to modernize the network.

General Information: The Exchange Codes (NXXs) in Numbering Plan Areas (NPAs) 212, 646, and 917 currently residing in the West 36th St. 2 NY 5E switch (see list in Table B below) will be moved to the Pearl St. NY C20 switch (see details in Table A below).

The native NPA NXXs belonging to the West 36th St. 2 NY 5E switch will be rehomed upon decommissioning of the switch and reflected in the Local Exchange Routing Guide (LERG) for the Pearl St. NY C20 switch. This will occur on or after June 1, 2025.

Table A

	From	To
Entity	West 36th St. 2 36DS1	Pearl St. PSPS1
CLLI	NYCMNY36DS1	NYCMNYPSPS1
Product	5E	C20
Location	230 West 36th Street New York, NY 10018	375 Pearl Street New York, NY 10038
Point Code	247 040 033	247 040 042
NXX Type	EOC	EOC
OCN	9104	9104
Rate Center Lata	132	132
Rate Center	NWYRCYZN01	NWYRCYZN01
State	NY	NY

Table B

NPA	NXX	TYPE	Switch
212	239	EOC	NYCMNY36DS1
212	244	EOC	NYCMNY36DS1
212	268	EOC	NYCMNY36DS1
212	279	EOC	NYCMNY36DS1
212	290	EOC	NYCMNY36DS1
212	296	EOC	NYCMNY36DS1
212	330	EOC	NYCMNY36DS1
212	465	EOC	NYCMNY36DS1
212	502	EOC	NYCMNY36DS1
212	526	EOC	NYCMNY36DS1
212	560	EOC	NYCMNY36DS1
212	563	EOC	NYCMNY36DS1
212	594	EOC	NYCMNY36DS1

212	609	EOC	NYCMNY36DS1
212	613	EOC	NYCMNY36DS1
212	615	EOC	NYCMNY36DS1
212	629	EOC	NYCMNY36DS1
212	631	EOC	NYCMNY36DS1
212	714	EOC	NYCMNY36DS1
212	736	EOC	NYCMNY36DS1
212	760	EOC	NYCMNY36DS1
212	868	EOC	NYCMNY36DS1
212	946	EOC	NYCMNY36DS1
212	947	EOC	NYCMNY36DS1
212	971	EOC	NYCMNY36DS1
646	674	EOC	NYCMNY36DS1
917	339	EOC	NYCMNY36DS1

Network Changes and Trunk Rearrangements:

The Pearl St. NY C20 switch will be the recipient office of traffic migrated from the West 36th St. 2 NY 5E switch. Traffic bound for the codes listed in Table B will be delivered via the 37th St. NY 23T 5E tandem local and LD FG (NYCMNY3723T intra-lata SHA / inter-lata FG Access SHA).

After all traffic is migrated off of the West 36th St. 2 NY 5E switch, this switch will be retired and removed from the network.

CLECs, IXC's, IEC's, wireless carriers, and paging carriers will need to secure new trunk groups built to the Pearl St. NY C20 switch or have existing trunk groups to that switch augmented. Carriers that have direct end office trunk (DEOT) with access connectivity in the West 36th St. 2 NY 5E switch will be required to reposition the codes to the Pearl St. NY C20 switch.

All ASRs for the Pearl St. NY C20 switch must be received no later than April 1, 2025, to provide sufficient time to migrate the traffic described above. All traffic must be moved by June 1, 2025.

Please adhere to industry standards using normal procedures that pertain to updates and changes to the LERG for all NXXs subject to the retirement of the West 36th St. 2 NY 5E switch.

For inquiries related to the proposed network reconfiguration, or to arrange a meeting with Verizon Network Engineering and Planning personnel, please contact your Verizon Account Manager.

We look forward to working with your team to enable uninterrupted service during the network redesign and transitioning of your traffic.